


Chapter 8 ■ Fatigue



1 ksi  
= 6.895 MPa

FIGURE 8.24 Notch sensitivity curves (after [9]). Note: (1) Here  $r$  is the radius at the point where the potential fatigue crack originates. (2) For  $r > 0.16$  in., extrapolate or use  $q \approx 1$ .