

## Type J (Iron-Constantan) Calibration

$$T = a_0 + a_1 V + a_2 V^2 + a_3 V^3 + a_4 V^4 + a_5 V^5$$

