

4.12 ■ Stress Concentration Factors, K_t




FIGURE 4.35 Shaft with fillet (a) bending; (b) axial load; (c) torsion. [7].