

DDEC® Reports - Trip Activity

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904

Trip Distance 267485.2 mi
Trip Fuel 42595.02 gal
Fuel Economy 6.28 mpg
Avg Drive Load 47 %
Avg Vehicle Speed 52.5 mph

Trip Time 7939:58:47
Fuel Consumption 5.36 gal/h
Idle Time 2839:35:04
Idle Percent 35.76 %
Idle Fuel 1670.27 gal
Parked Regen Time 9:27:57

Driving

Time 5090:55:46
Percent 64.12 %
Fuel 40924.75 gal
Economy 6.54 mpg

Stop Idle

Time 2421:38:57
Percent 30.50 %
Fuel 1372.00 gal

Vehicle Speed Limiting

Time 1882:24:35
Percent 36.98 %
Distance 119264.0 mi
Fuel 12406.25 gal

Over Rev Limit

Count 110
Time 0:38:18
Percent 0.01 %

Top Gear

Time 3959:32:17
Percent 77.78 %
Distance 238661.7 mi
Fuel 33670.63 gal

Highest RPM

2573 rpm
Occurred 07/16/13 18:27:34 (EST)

Top Gear - 1

Time 343:52:18
Percent 6.75 %
Distance 14954.2 mi
Fuel 3271.38 gal

Diag. Records

890
Hard Brake Count 70
Firm Brake Count 2688
Brake Count 73835
Eng. Brake Time 191:50:19

Cruise

Time 1275:08:55
Percent 25.05 %
Distance 78774.5 mi
Fuel 11233.38 gal

Fan On Time

Total Time 1640:52:55
Engine System 105:49:04
Manual 0:00:00
A/C 1527:39:29
DPF Fan Time 7:24:22

Top Gear Cruise

Time 1263:25:21
Percent 24.82 %
Distance 78253.5 mi
Fuel 11086.38 gal

Engine Utilization

32.12 %

Vehicle Utilization

20.59 %

DPF Regeneration

Parked Completed 16
Parked Regen Fuel 51.77 gal
Driving Completed 148
Driving Regen Fuel 360.46 gal

Speeding A(>=66 and <71 mph)

Count 22389
Time 94:42:51
Percent 1.86 %

Diesel Exhaust Fluid (DEF)

Trip Fluid 1154.38 gal
Trip Percent 2.71 %
Trip Economy 231.71 mpg
Driving Fluid 1138.21 gal
Driving Economy 235.00 mpg

Speeding B(>=71 mph)

Count 2377
Time 11:22:02
Percent 0.22 %

Optimized Idle Time

Active 0:00:00
Run 0:00:00
Battery 0:00:00
Engine Temp. 0:00:00
Thermostat 0:00:00
Extended Idle 0:00:00
Continuous 0:00:00

Highest Speed

88.0 mph
Occurred 02/09/14 8:30:50 (EST)

Optimized Idle Battery Charging Starts

Normal Count 0
Alternate Count 0
Continuous Run 0

Coasting Time

0:10:24

Coasting Percent

0.00 %

DDEC® Reports - Trip Activity

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904

Trip Distance	267485.2 mi	Trip Time	7939:58:47
Trip Fuel	42595.02 gal	Fuel Consumption	5.36 gal/h
Fuel Economy	6.28 mpg	Idle Time	2839:35:04
Avg Drive Load	47 %	Idle Percent	35.76 %
Avg Vehicle Speed	52.5 mph	Idle Fuel	1670.27 gal
		Parked Regen Time	9:27:57

Predictive Cruise Control

Time	0:00:00
Percent	0.00 %
Distance	0.0 mi
Fuel	0.00 gal

VSG (PTO)

Total Time	216:28:59
Percent	2.73 %
Total Fuel	161.38 gal
Working Time	0:00:29
Working Fuel	0.00 gal

DDEC® Reports - Monthly Activity

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Partial Month: May, 2014 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904

Trip Distance	49.6 mi	Trip Time	7:01:00
Trip Fuel	10.13 gal	Fuel Consumption	1.44 gal/h
Fuel Economy	4.90 mpg	Idle Time	5:14:11
Avg Drive Load	23 %	Idle Percent	74.63 %
Avg Vehicle Speed	27.9 mph	Idle Fuel	4.00 gal
		Parked Regen Time	0:00:00

Driving

Time	1:46:49
Percent	25.37 %
Fuel	6.13 gal
Economy	8.10 mpg

Vehicle Speed Limiting

Time	0:18:18
Percent	17.13 %
Distance	19.4 mi
Fuel	1.75 gal

Top Gear

Time	0:33:37
Percent	31.47 %
Distance	32.0 mi
Fuel	2.88 gal

Top Gear - 1

Time	0:08:12
Percent	7.68 %
Distance	5.9 mi
Fuel	0.63 gal

Cruise

Time	0:12:02
Percent	11.27 %
Distance	12.6 mi
Fuel	1.25 gal

Top Gear Cruise

Time	0:12:02
Percent	11.27 %
Distance	12.6 mi
Fuel	1.25 gal

Speeding A(>=66 and <71 mph)

Count	0
Time	0:00:00
Percent	0.00 %

Speeding B(>=71 mph)

Count	0
Time	0:00:00
Percent	0.00 %

Highest Speed

64.0 mph
Occurred 05/28/14 7:43:42 (EST)

Coasting Time

0:00:00

Coasting Percent

0.00 %

Stop Idle

Time	3:53:02
Percent	55.35 %
Fuel	2.63 gal

Over Rev Limit

1800 rpm

Count	0
Time	0:00:00
Percent	0.00 %

Highest RPM

1955 rpm

Occurred 05/16/14 12:56:55 (EST)

Diag. Records

26

Hard Brake Count

2

Firm Brake Count

2

Brake Count

79

Eng. Brake Time

0:00:23

Fan On Time

Total Time	2:02:38
Engine System	0:00:00
Manual	0:00:00
A/C	2:02:38
DPF Fan Time	0:00:00

Engine Utilization

1.06 %

Vehicle Utilization

0.27 %

DPF Regeneration

Parked Completed	0
Parked Regen Fuel	0.00 gal
Driving Completed	0
Driving Regen Fuel	0.28 gal

Diesel Exhaust Fluid (DEF)

Trip Fluid	0.07 gal
Trip Percent	0.70 %
Trip Economy	700.56 mpg
Driving Fluid	0.07 gal
Driving Economy	746.92 mpg

Optimized Idle Time

Active	0:00:00
Run	0:00:00
Battery	0:00:00
Engine Temp.	0:00:00
Thermostat	0:00:00
Extended Idle	0:00:00
Continuous	0:00:00

Optimized Idle Battery Charging Starts

Normal Count	0
Alternate Count	0
Continuous Run	0

DDEC® Reports - Monthly Activity

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Partial Month: May, 2014 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904

Trip Distance	49.6 mi	Trip Time	7:01:00
Trip Fuel	10.13 gal	Fuel Consumption	1.44 gal/h
Fuel Economy	4.90 mpg	Idle Time	5:14:11
Avg Drive Load	23 %	Idle Percent	74.63 %
Avg Vehicle Speed	27.9 mph	Idle Fuel	4.00 gal
		Parked Regen Time	0:00:00

Predictive Cruise Control

Time	0:00:00
Percent	0.00 %
Distance	0.0 mi
Fuel	0.00 gal

VSG (PTO)

Total Time	0:34:51
Percent	8.28 %
Total Fuel	0.63 gal
Working Time	0:00:00
Working Fuel	0.00 gal

DDEC® Reports - Monthly Activity

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Month: April, 2014 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904

Trip Distance	0.1 mi	Trip Time	0:05:54
Trip Fuel	0.00 gal	Fuel Consumption	0.00 gal/h
Fuel Economy	0.00 mpg	Idle Time	0:05:27
Avg Drive Load	22 %	Idle Percent	92.37 %
Avg Vehicle Speed	13.3 mph	Idle Fuel	0.00 gal
		Parked Regen Time	0:00:00

Driving

Time	0:00:27
Percent	7.63 %
Fuel	0.00 gal
Economy	0.00 mpg

Vehicle Speed Limiting

Time	0:00:00
Percent	0.00 %
Distance	0.0 mi
Fuel	0.00 gal

Top Gear

Time	0:00:00
Percent	0.00 %
Distance	0.0 mi
Fuel	0.00 gal

Top Gear - 1

Time	0:00:00
Percent	0.00 %
Distance	0.0 mi
Fuel	0.00 gal

Cruise

Time	0:00:00
Percent	0.00 %
Distance	0.0 mi
Fuel	0.00 gal

Top Gear Cruise

Time	0:00:00
Percent	0.00 %
Distance	0.0 mi
Fuel	0.00 gal

Speeding A(>=66 and <71 mph)

Count	0
Time	0:00:00
Percent	0.00 %

Speeding B(>=71 mph)

Count	0
Time	0:00:00
Percent	0.00 %

Highest Speed

3.5 mph
Occurred 04/21/14 8:19:07 (EST)

Coasting Time

0:00:00

Coasting Percent

0.00 %

Stop Idle

Time	0:00:00
Percent	0.00 %
Fuel	0.00 gal

Over Rev Limit

1800 rpm	
Count	0
Time	0:00:00
Percent	0.00 %

Highest RPM

1463 rpm
Occurred 04/21/14 8:19:16 (EST)

Diag. Records

12	
Hard Brake Count	0
Firm Brake Count	0
Brake Count	0
Eng. Brake Time	0:00:00

Fan On Time

Total Time	0:00:00
Engine System	0:00:00
Manual	0:00:00
A/C	0:00:00
DPF Fan Time	0:00:00

Engine Utilization

0.01 %

Vehicle Utilization

0.00 %

DPF Regeneration

Parked Completed	0
Parked Regen Fuel	0.00 gal
Driving Completed	0
Driving Regen Fuel	0.00 gal

Diesel Exhaust Fluid (DEF)

Trip Fluid	0.00 gal
Trip Percent	0.00 %
Trip Economy	0.00 mpg
Driving Fluid	0.00 gal
Driving Economy	0.00 mpg

Optimized Idle Time

Active	0:00:00
Run	0:00:00
Battery	0:00:00
Engine Temp.	0:00:00
Thermostat	0:00:00
Extended Idle	0:00:00
Continuous	0:00:00

Optimized Idle Battery Charging Starts

Normal Count	0
Alternate Count	0
Continuous Run	0

DDEC® Reports - Monthly Activity

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Month: April, 2014 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904

Trip Distance	0.1 mi	Trip Time	0:05:54
Trip Fuel	0.00 gal	Fuel Consumption	0.00 gal/h
Fuel Economy	0.00 mpg	Idle Time	0:05:27
Avg Drive Load	22 %	Idle Percent	92.37 %
Avg Vehicle Speed	13.3 mph	Idle Fuel	0.00 gal
		Parked Regen Time	0:00:00

Predictive Cruise Control

Time	0:00:00
Percent	0.00 %
Distance	0.0 mi
Fuel	0.00 gal

VSG (PTO)

Total Time	0:00:00
Percent	0.00 %
Total Fuel	0.00 gal
Working Time	0:00:00
Working Fuel	0.00 gal

DDEC® Reports - Monthly Activity

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Month: March, 2014 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904

Trip Distance 4111.3 mi
Trip Fuel 690.20 gal
Fuel Economy 5.96 mpg
Avg Drive Load 49 %
Avg Vehicle Speed 53.0 mph

Trip Time 116:21:34
Fuel Consumption 5.93 gal/h
Idle Time 38:49:06
Idle Percent 33.36 %
Idle Fuel 32.33 gal
Parked Regen Time 0:29:32

Driving

Time 77:32:28
Percent 66.64 %
Fuel 657.88 gal
Economy 6.25 mpg

Stop Idle

Time 30:53:42
Percent 26.55 %
Fuel 25.25 gal

Vehicle Speed Limiting

Time 35:42:58
Percent 46.06 %
Distance 2266.2 mi
Fuel 240.38 gal

Over Rev Limit

Count 0
Time 0:00:03
Percent 0.00 %

Top Gear

Time 59:44:57
Percent 77.05 %
Distance 3672.8 mi
Fuel 522.25 gal

Highest RPM

2206 rpm
Occurred 03/18/14 11:16:28 (EST)

Top Gear - 1

Time 4:57:00
Percent 6.38 %
Distance 215.7 mi
Fuel 57.75 gal

Diag. Records

6
Hard Brake Count 2
Firm Brake Count 66
Brake Count 1083
Eng. Brake Time 1:18:25

Cruise

Time 21:22:16
Percent 27.56 %
Distance 1320.4 mi
Fuel 157.75 gal

Fan On Time

Total Time 9:03:29
Engine System 0:24:21
Manual 0:00:00
A/C 8:10:38
DPF Fan Time 0:28:30

Top Gear Cruise

Time 21:08:04
Percent 27.26 %
Distance 1309.6 mi
Fuel 156.13 gal

Engine Utilization

15.64 %

Vehicle Utilization

10.42 %

DPF Regeneration

Parked Completed 1
Parked Regen Fuel 1.95 gal
Driving Completed 3
Driving Regen Fuel 5.65 gal

Speeding A(>=66 and <71 mph)

Count 605
Time 2:32:15
Percent 3.27 %

Diesel Exhaust Fluid (DEF)

Trip Fluid 20.22 gal
Trip Percent 2.93 %
Trip Economy 203.32 mpg
Driving Fluid 20.08 gal
Driving Economy 204.73 mpg

Speeding B(>=71 mph)

Count 166
Time 1:06:48
Percent 1.44 %

Optimized Idle Time

Active 0:00:00
Run 0:00:00
Battery 0:00:00
Engine Temp. 0:00:00
Thermostat 0:00:00
Extended Idle 0:00:00
Continuous 0:00:00

Highest Speed

85.0 mph
Occurred 03/18/14 12:04:41 (EST)

Optimized Idle Battery Charging Starts

Normal Count 0
Alternate Count 0
Continuous Run 0

Coasting Time

0:00:18

Coasting Percent

0.01 %

DDEC® Reports - Monthly Activity

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Month: March, 2014 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904

Trip Distance	4111.3 mi	Trip Time	116:21:34
Trip Fuel	690.20 gal	Fuel Consumption	5.93 gal/h
Fuel Economy	5.96 mpg	Idle Time	38:49:06
Avg Drive Load	49 %	Idle Percent	33.36 %
Avg Vehicle Speed	53.0 mph	Idle Fuel	32.33 gal
		Parked Regen Time	0:29:32

Predictive Cruise Control

Time	0:00:00
Percent	0.00 %
Distance	0.0 mi
Fuel	0.00 gal

VSG (PTO)

Total Time	28:51:54
Percent	24.81 %
Total Fuel	24.38 gal
Working Time	0:00:03
Working Fuel	0.00 gal

DDEC® Reports - Configuration

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904

Trip Distance	267485.2	mi	Trip Time	7939:58:47					
Trip Fuel	42595.02	gal	Fuel Consumption	5.36 gal/h					
Fuel Economy	6.28	mpg	Idle Time	2839:35:04					
Avg Drive Load	47	%	Idle Percent	35.76 %					
Avg Vehicle Speed	52.5	mph	Idle Fuel	1670.27 gal					
			Parked Regen Time	9:27:57					
Hard Brake Limit	7.0	mph/s							
Stop Idle Limit	5	min							
Top Gear Limit	22	rpm/mph							
Top Gear-1 Limit	30	rpm/mph	Learned On:	05/07/2014 (EST)					
ECM S/W	R22_02_000a								
ECM Type	DDEC 10								
Config. Change	05/28/2014 (EST)								
Idle Method	VSS								
Idle-Load Limit	-								
Idle-RPM Limit	-								
Working PTO RPM Limit	900	rpm							
Working PTO Load Limit	30	%							
Firm Brake Limit	4	mph/s							
Reset Lockout	No								
Fleet Time Zone	-5.0	h							
Maintenance Visual Reminder:									
Enable	No								
Percent	-								
Vehicle Speed Bands (mph)	10	20	30	40	50	55	60	66	71
Engine Speed Bands (rpm)	700	1000	1200	1300	1400	1500	1600	1700	1800
Percent Load Bands (%)	10	20	30	40	50	60	70	80	90

Trip Reset Status

4 Extracted but did not reset!

DDEC® Reports - Life-To-Date

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904

Trip Distance 267485.2 mi
Trip Fuel 42595.02 gal
Fuel Economy 6.28 mpg
Avg Drive Load 47 %
Avg Vehicle Speed 52.5 mph

Trip Time 7939:58:47
Fuel Consumption 5.36 gal/h
Idle Time 2839:35:04
Idle Percent 35.76 %
Idle Fuel 1670.27 gal
Parked Regen Time 9:27:57

Total Distance 346469.4 mi
Total Time 10477:56:17
Total Fuel 55794.27 gal
Overall Fuel Economy 6.21 mpg
Avg Vehicle Speed 33.07 mph

Idle Time 3946:34:46
Idle Percent 37.67 %
Idle Fuel 2425.88 gal

VSG(PTO) Total Time 727:15:22
VSG(PTO) Percent 6.94 %
VSG(PTO) Total Fuel 564.63 gal
VSG(PTO) Working Time 0:01:47
VSG(PTO) Working Fuel 0.13 gal

Cruise Percent 24.60 %
Cruise Time 1606:46:36

Eng. Brake Time 220:18:14
Revolutions/mi 1935
Average RPM 1066

DPF Regeneration

Parked Completed 25
Occurred 03/17/14 07:48 (EST)
Driving Completed 195
Occurred 03/18/14 10:37 (EST)

Predictive Cruise Control

Time 0:00:00
Percent 0.00 %

Avg. Drive Load 47 %

Optimized Idle Time

Active Time 0:00:00
Run Time 0:00:00

Optimized Idle Battery Charging Starts

Normal Count 0
Alternate Count 0
Continuous Run 0

Fan On Time

Total Time 2310:22:23
Engine System 146:55:59
Manual 0:00:00
A/C 2163:26:24
DPF Fan Time 10:29:33

Peak Road Speed 80.5 mph

Occurred 03/11/14 20:37 (EST)

Peak Engine RPM 2573 rpm

Occurred 07/16/13 18:27 (EST)

Parked Regen Fuel 69.25 gal

Driving Regen Fuel 478.98 gal

Parked Regen Time 12:33:12

Diesel Exhaust Fluid (DEF)

Total Fluid 1473.13 gal
Total Percent 2.64 %
Total Economy 235.19 mpg
Driving Fluid 1452.13 gal
Driving Economy 238.59 mpg

DDEC® Reports - Vehicle Speed/RPM

Print Date: 5/28/2014 11:49 AM


Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904


Trip Distance 267485.2 mi
Trip Fuel 42595.02 gal
Fuel Economy 6.28 mpg
Avg Drive Load 47 %
Avg Vehicle Speed 52.5 mph

Trip Time 7939:58:47
Fuel Consumption 5.36 gal/h
Idle Time 2839:35:04
Idle Percent 35.76 %
Idle Fuel 1670.27 gal
Parked Regen Time 9:27:57

Vehicle Speed Histogram



Engine Speed Histogram



Percent of Trip Time in Speed and RPM Table

Vehicle Speed (mph)

Engine RPM	0- 9	10-19	20-29	30-39	40-49	50-54	55-59	60-65	66-70	71+	Total
0- 699	33.4	0.4	0.2	0.1							34.1
700- 999	4.9	0.4	0.3	0.4	0.4						6.3
1000-1199	0.9	0.5	0.6	0.8	1.5	2.8					7.1
1200-1299	0.2	0.2	0.4	0.3	0.6	2.0	5.7				9.5
1300-1399	0.2	0.2	0.2	0.4	0.9		5.3	8.0			15.1
1400-1499	0.1	0.2	0.2	0.3	0.8			22.6	0.5		24.7
1500-1599	0.1	0.1	0.2	0.3	0.2	0.5			0.7		2.1
1600-1699	0.1	0.1	0.1	0.1		0.3				0.1	0.9
1700-1799											0.2
1800+											
Total	39.8	2.1	2.2	2.7	4.5	5.6	11.1	30.7	1.2	0.1	
Brakes	14451	8969	10116	9652	10143	5981	6365	6139	1468	551	73835
Hard Brakes			22	26	12	5	4	1			70
Firm Brakes		186	1003	696	471	158	126	47		1	2688

Note: This table contains values <0.005 percent of trip time



DDEC® Reports - Engine Load/RPM

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904

Trip Distance	267485.2 mi	Trip Time	7939:58:47
Trip Fuel	42595.02 gal	Fuel Consumption	5.36 gal/h
Fuel Economy	6.28 mpg	Idle Time	2839:35:04
Avg Drive Load	47 %	Idle Percent	35.76 %
Avg Vehicle Speed	52.5 mph	Idle Fuel	1670.27 gal
		Parked Regen Time	9:27:57



Percent of Trip Time in Load and RPM Table

Engine Load (%)

Engine RPM	0- 9	10-19	20-29	30-39	40-49	50-59	60-69	70-79	80-89	90-100	Total
0- 699	14.9	17.3	1.3	0.3	0.1	0.1					34.1
700- 999	2.2	3.0	0.4	0.2	0.1	0.1	0.1	0.1		0.2	6.3
1000-1199	1.9	0.8	0.5	0.4	0.4	0.4	0.3	0.3	0.3	1.7	7.1
1200-1299	1.8	0.6	0.6	0.7	0.8	0.7	0.6	0.6	0.5	2.7	9.5
1300-1399	2.2	0.8	0.9	1.1	1.3	1.2	1.2	1.3	1.1	4.2	15.1
1400-1499	3.9	1.9	1.6	2.5	3.6	3.5	3.1	1.5	0.9	2.1	24.7
1500-1599	1.0	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.5	2.1
1600-1699	0.3	0.1	0.1	0.1	0.1	0.1				0.1	0.9
1700-1799	0.1										0.2
1800+											
Total	28.3	24.5	5.5	5.3	6.5	6.0	5.5	3.9	3.0	11.6	

Note: This table contains values <0.005 percent of trip time

DDEC® Reports - Over Speed/Over Rev


Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975


Trip: 08/02/11 07:52:13 To 05/28/14 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904

Trip Distance	267485.2 mi	Trip Time	7939:58:47
Trip Fuel	42595.02 gal	Fuel Consumption	5.36 gal/h
Fuel Economy	6.28 mpg	Idle Time	2839:35:04
Avg Drive Load	47 %	Idle Percent	35.76 %
Avg Vehicle Speed	52.5 mph	Idle Fuel	1670.27 gal
		Parked Regen Time	9:27:57

Over Speed Histogram



Over Rev Histogram



Percent of Trip Time in Over Speed and Over Rev Bands

Vehicle Speed(mph)

71-72	73-74	75-76	77-78	79-80	81-82	83-84	85-86	87-88	89+
0.08	0.04	0.01	0.01	<0.005	<0.005	<0.005	<0.005	<0.005	

Engine Speed(rpm)

1800 1899	1900 1999	2000 2099	2100 2199	2200 2299	2300 2399	2400 2499	2500 2599	2600 2699	2700+
0.03	<0.005	<0.005	<0.005	<0.005	<0.005				

DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975


Vehicle ID:

1556

Driver ID:

Engine S/N:

472903S0045904



DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975


Vehicle ID:

1556

Driver ID:

Engine S/N:

472903S0045904



DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:


1556

Driver ID:


Engine S/N:

472903S0045904


(5/28/2014)




(5/27/2014)




(5/26/2014)




(5/25/2014)



(5/24/2014)



(5/23/2014)



DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:


1556

Driver ID:


Engine S/N:

472903S0045904


(5/22/2014)




(5/21/2014)




(5/20/2014)




(5/19/2014)



(5/16/2014)



(5/15/2014)



DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:


1556

Driver ID:


Engine S/N:

472903S0045904


(5/13/2014)




(5/12/2014)




(5/7/2014)




(4/21/2014)



(3/28/2014)



(3/26/2014)



DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:


1556

Driver ID:


Engine S/N:

472903S0045904


(3/25/2014)




(3/24/2014)




(3/22/2014)




(3/21/2014)



(3/20/2014)



(3/19/2014)



DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:


1556

Driver ID:


Engine S/N:

472903S0045904


(3/18/2014)




(3/17/2014)




(3/16/2014)




(3/15/2014)



(3/14/2014)



(3/13/2014)



DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:

1556

Driver ID:

Engine S/N:

472903S0045904

Date:	5/28/2014
Start Time:	05:53:11 EST
Odometer:	346436.70 mi
Distance:	32.70 mi
Fuel:	5.00 gal
Fuel Economy:	6.54 mpg
Average Speed:	40.88 mph
DEF Fluid:	0.07 gal
Trip Economy:	461.86 mpg

Total (hh:mm)	00:48	02:23	20:49
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	1	0	119
06:00-08:00	28	2	90
08:00-10:00	19	101	0
10:00-12:00	0	40	80
12:00-14:00	0	0	120
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	5/27/2014
Start Time:	12:01:30 EST
Odometer:	346436.70 mi
Distance:	0.00 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	0.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:00	00:02	23:58
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	0	0	120
10:00-12:00	0	0	120
12:00-14:00	0	2	118
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	5/26/2014
Start Time:	16:09:13 EST
Odometer:	346436.60 mi
Distance:	0.10 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	0.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:00	00:01	23:59
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	0	0	120
10:00-12:00	0	0	120
12:00-14:00	0	0	120
14:00-16:00	0	0	120
16:00-18:00	0	1	119
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:

1556

Driver ID:

Engine S/N:

472903S0045904

Date:	5/25/2014
Start Time:	14:22:07 EST
Odometer:	346436.40 mi
Distance:	0.20 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	6.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:02	00:02	23:56
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	0	0	120
10:00-12:00	0	0	120
12:00-14:00	0	0	120
14:00-16:00	2	2	116
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	5/24/2014
Start Time:	05:51:51 EST
Odometer:	346436.30 mi
Distance:	0.10 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	6.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:01	00:01	23:58
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	1	1	118
08:00-10:00	0	0	120
10:00-12:00	0	0	120
12:00-14:00	0	0	120
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	5/23/2014
Start Time:	19:04:40 EST
Odometer:	346436.20 mi
Distance:	0.10 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	3.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:02	00:04	23:54
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	0	0	120
10:00-12:00	0	0	120
12:00-14:00	0	0	120
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	2	1	117
20:00-22:00	0	1	119
22:00-24:00	0	2	118

DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:

1556

Driver ID:

Engine S/N:

472903S0045904

Date:	5/22/2014
Start Time:	19:04:47 EST
Odometer:	346436.00 mi
Distance:	0.20 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	12.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:01	00:00	23:59
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	0	0	120
10:00-12:00	0	0	120
12:00-14:00	0	0	120
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	1	0	119
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	5/21/2014
Start Time:	08:41:23 EST
Odometer:	346435.50 mi
Distance:	0.50 mi
Fuel:	0.25 gal
Fuel Economy:	2.00 mpg
Average Speed:	5.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:06	00:30	23:24
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	0	0	120
10:00-12:00	2	7	111
12:00-14:00	1	2	117
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	1	2	117
20:00-22:00	2	19	99
22:00-24:00	0	0	120

Date:	5/20/2014
Start Time:	06:51:21 EST
Odometer:	346435.40 mi
Distance:	0.10 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	0.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:00	00:10	23:50
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	5	115
08:00-10:00	0	2	118
10:00-12:00	0	0	120
12:00-14:00	0	0	120
14:00-16:00	0	3	117
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:

1556

Driver ID:

Engine S/N:

472903S0045904

Date:	5/19/2014
Start Time:	14:42:28 EST
Odometer:	346434.10 mi
Distance:	1.30 mi
Fuel:	0.75 gal
Fuel Economy:	1.73 mpg
Average Speed:	6.50 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:12	00:20	23:28
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	0	0	120
10:00-12:00	0	0	120
12:00-14:00	0	0	120
14:00-16:00	12	20	88
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	5/16/2014
Start Time:	08:08:17 EST
Odometer:	346419.90 mi
Distance:	14.20 mi
Fuel:	1.50 gal
Fuel Economy:	9.47 mpg
Average Speed:	29.38 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:29	00:19	23:12
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	5	8	107
10:00-12:00	5	8	107
12:00-14:00	19	3	98
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	5/15/2014
Start Time:	09:02:43 EST
Odometer:	346419.80 mi
Distance:	0.10 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	0.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:00	00:07	23:53
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	0	7	113
10:00-12:00	0	0	120
12:00-14:00	0	0	120
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:

1556

Driver ID:

Engine S/N:

472903S0045904

Date:	5/13/2014
Start Time:	11:58:12 EST
Odometer:	346419.80 mi
Distance:	0.00 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	0.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:00	00:04	23:56
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	0	0	120
10:00-12:00	0	0	120
12:00-14:00	0	4	116
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	5/12/2014
Start Time:	10:35:35 EST
Odometer:	346419.80 mi
Distance:	0.00 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	0.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:00	00:04	23:56
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	0	0	120
10:00-12:00	0	4	116
12:00-14:00	0	0	120
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	5/7/2014
Start Time:	09:04:54 EST
Odometer:	346419.80 mi
Distance:	0.00 mi
Fuel:	0.50 gal
Fuel Economy:	0.00 mpg
Average Speed:	0.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:00	00:56	23:04
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	0	0	120
10:00-12:00	0	6	114
12:00-14:00	0	50	70
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:

1556

Driver ID:

Engine S/N:

472903S0045904

Date:	4/21/2014
Start Time:	08:13:21 EST
Odometer:	346419.70 mi
Distance:	0.10 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	6.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:01	00:04	23:55
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	1	4	115
10:00-12:00	0	0	120
12:00-14:00	0	0	120
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	3/28/2014
Start Time:	10:42:13 EST
Odometer:	346419.70 mi
Distance:	0.00 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	0.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:00	00:02	23:58
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	0	0	120
10:00-12:00	0	0	120
12:00-14:00	0	0	120
14:00-16:00	0	2	118
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	3/26/2014
Start Time:	10:01:38 EST
Odometer:	346419.70 mi
Distance:	0.00 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	0.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:00	00:00	24:00
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	0	0	120
10:00-12:00	0	0	120
12:00-14:00	0	0	120
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:

1556

Driver ID:

Engine S/N:

472903S0045904

Date:	3/25/2014
Start Time:	12:19:36 EST
Odometer:	346419.60 mi
Distance:	0.10 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	0.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:00	00:01	23:59
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	0	0	120
10:00-12:00	0	0	120
12:00-14:00	0	1	119
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	3/24/2014
Start Time:	05:45:35 EST
Odometer:	346419.60 mi
Distance:	0.00 mi
Fuel:	0.00 gal
Fuel Economy:	0.00 mpg
Average Speed:	0.00 mph
DEF Fluid:	0.00 gal
Trip Economy:	0.00 mpg

Total (hh:mm)	00:00	00:02	23:58
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	2	118
06:00-08:00	0	0	120
08:00-10:00	0	0	120
10:00-12:00	0	0	120
12:00-14:00	0	0	120
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	3/22/2014
Start Time:	05:35:13 EST
Odometer:	346087.80 mi
Distance:	331.80 mi
Fuel:	44.00 gal
Fuel Economy:	7.54 mpg
Average Speed:	57.54 mph
DEF Fluid:	1.29 gal
Trip Economy:	257.69 mpg

Total (hh:mm)	05:46	00:31	17:43
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	5	115
06:00-08:00	21	8	91
08:00-10:00	97	4	19
10:00-12:00	62	2	56
12:00-14:00	120	0	0
14:00-16:00	44	8	68
16:00-18:00	2	4	114
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:

1556

Driver ID:

Engine S/N:

472903S0045904

Date:	3/21/2014
Start Time:	03:16:20 EST
Odometer:	345761.90 mi
Distance:	325.90 mi
Fuel:	43.75 gal
Fuel Economy:	7.45 mpg
Average Speed:	56.03 mph
DEF Fluid:	1.35 gal
Trip Economy:	241.48 mpg

Total (hh:mm)	05:49	02:19	15:52
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	43	77
04:00-06:00	1	61	58
06:00-08:00	32	7	81
08:00-10:00	11	2	107
10:00-12:00	0	0	120
12:00-14:00	3	4	113
14:00-16:00	65	20	35
16:00-18:00	120	0	0
18:00-20:00	111	1	8
20:00-22:00	6	1	113
22:00-24:00	0	0	120

Date:	3/20/2014
Start Time:	01:25:04 EST
Odometer:	345694.00 mi
Distance:	67.90 mi
Fuel:	5.75 gal
Fuel Economy:	11.81 mpg
Average Speed:	45.27 mph
DEF Fluid:	0.13 gal
Trip Economy:	505.67 mpg

Total (hh:mm)	01:30	00:20	22:10
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	18	102
04:00-06:00	0	0	120
06:00-08:00	0	0	120
08:00-10:00	1	0	119
10:00-12:00	0	0	120
12:00-14:00	89	2	29
14:00-16:00	0	0	120
16:00-18:00	0	0	120
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	3/19/2014
Start Time:	04:55:52 EST
Odometer:	345651.40 mi
Distance:	42.60 mi
Fuel:	8.00 gal
Fuel Economy:	5.33 mpg
Average Speed:	41.23 mph
DEF Fluid:	0.21 gal
Trip Economy:	200.10 mpg

Total (hh:mm)	01:02	00:50	22:08
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	7	32	81
06:00-08:00	0	7	113
08:00-10:00	38	1	81
10:00-12:00	0	3	117
12:00-14:00	17	5	98
14:00-16:00	0	0	120
16:00-18:00	0	2	118
18:00-20:00	0	0	120
20:00-22:00	0	0	120
22:00-24:00	0	0	120

DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:

1556

Driver ID:

Engine S/N:

472903S0045904

Date:	3/18/2014
Start Time:	06:41:33 EST
Odometer:	345098.20 mi
Distance:	553.20 mi
Fuel:	90.25 gal
Fuel Economy:	6.13 mpg
Average Speed:	57.93 mph
DEF Fluid:	2.69 gal
Trip Economy:	205.69 mpg

Total (hh:mm)	09:33	00:59	13:28
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	28	41	51
08:00-10:00	120	0	0
10:00-12:00	120	0	0
12:00-14:00	120	0	0
14:00-16:00	45	1	74
16:00-18:00	0	1	119
18:00-20:00	65	8	47
20:00-22:00	75	8	37
22:00-24:00	0	0	120

Date:	3/17/2014
Start Time:	00:00:00 EST
Odometer:	344867.00 mi
Distance:	231.20 mi
Fuel:	46.00 gal
Fuel Economy:	5.03 mpg
Average Speed:	46.09 mph
DEF Fluid:	1.31 gal
Trip Economy:	176.88 mpg

Total (hh:mm)	05:01	08:22	10:37
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	120	0
02:00-04:00	0	120	0
04:00-06:00	0	120	0
06:00-08:00	13	106	1
08:00-10:00	118	2	0
10:00-12:00	5	1	114
12:00-14:00	79	9	32
14:00-16:00	5	5	110
16:00-18:00	2	3	115
18:00-20:00	54	14	52
20:00-22:00	25	2	93
22:00-24:00	0	0	120

Date:	3/16/2014
Start Time:	06:57:54 EST
Odometer:	344435.70 mi
Distance:	431.30 mi
Fuel:	83.00 gal
Fuel Economy:	5.20 mpg
Average Speed:	51.14 mph
DEF Fluid:	2.59 gal
Trip Economy:	166.60 mpg

Total (hh:mm)	08:26	03:36	11:58
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	0	120
06:00-08:00	8	24	88
08:00-10:00	16	22	82
10:00-12:00	0	2	118
12:00-14:00	48	6	66
14:00-16:00	120	0	0
16:00-18:00	91	29	0
18:00-20:00	117	3	0
20:00-22:00	106	10	4
22:00-24:00	0	120	0

DDEC® Reports - Daily Engine Usage

Print Date: 5/28/2014 11:49 AM

Date Range: 05/28/14 To 03/13/14 (EST)

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Vehicle ID:

1556

Driver ID:

Engine S/N:

472903S0045904

Date:	3/15/2014
Start Time:	05:03:58 EST
Odometer:	343889.90 mi
Distance:	545.80 mi
Fuel:	84.50 gal
Fuel Economy:	6.46 mpg
Average Speed:	57.86 mph
DEF Fluid:	2.71 gal
Trip Economy:	201.37 mpg

Total (hh:mm)	09:26	00:40	13:54
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	0	120
04:00-06:00	0	10	110
06:00-08:00	73	15	32
08:00-10:00	120	0	0
10:00-12:00	115	2	3
12:00-14:00	70	2	48
14:00-16:00	79	1	40
16:00-18:00	99	4	17
18:00-20:00	10	6	104
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	3/14/2014
Start Time:	02:48:53 EST
Odometer:	343771.60 mi
Distance:	118.30 mi
Fuel:	18.75 gal
Fuel Economy:	6.31 mpg
Average Speed:	40.10 mph
DEF Fluid:	0.50 gal
Trip Economy:	237.53 mpg

Total (hh:mm)	02:57	02:03	19:00
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	3	67	50
04:00-06:00	15	26	79
06:00-08:00	75	1	44
08:00-10:00	1	4	115
10:00-12:00	0	0	120
12:00-14:00	12	3	105
14:00-16:00	1	10	109
16:00-18:00	3	0	117
18:00-20:00	67	12	41
20:00-22:00	0	0	120
22:00-24:00	0	0	120

Date:	3/13/2014
Start Time:	03:52:25 EST
Odometer:	343271.40 mi
Distance:	500.20 mi
Fuel:	93.50 gal
Fuel Economy:	5.35 mpg
Average Speed:	56.20 mph
DEF Fluid:	3.19 gal
Trip Economy:	156.85 mpg

Total (hh:mm)	08:54	00:54	14:12
Hour (EST)	Drive (min)	Idle (min)	Off (min)
00:00-02:00	0	0	120
02:00-04:00	0	6	114
04:00-06:00	0	13	107
06:00-08:00	89	31	0
08:00-10:00	120	0	0
10:00-12:00	120	0	0
12:00-14:00	70	2	48
14:00-16:00	0	0	120
16:00-18:00	105	2	13
18:00-20:00	30	0	90
20:00-22:00	0	0	120
22:00-24:00	0	0	120

DDEC® Reports - Hard Brake

#1

Print Date: 5/28/2014 11:49 AM
Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904


Trip Distance 267485.2 mi
Trip Fuel 42595.02 gal
Fuel Economy 6.28 mpg
Avg Drive Load 47 %
Avg Vehicle Speed 52.5 mph

Trip Time 7939:58:47
Fuel Consumption 5.36 gal/h
Idle Time 2839:35:04
Idle Percent 35.76 %
Idle Fuel 1670.27 gal
Parked Regen Time 9:27:57


Incident Time: 05/16/14 11:41:08 (EST)

Incident Odometer: 346421.8 mi


Vehicle Speed (mph)




Engine RPM




Percent



Brake



Clutch



DDEC® Reports - Hard Brake

#2

Print Date: 5/28/2014 11:49 AM
Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904


Trip Distance 267485.2 mi
Trip Fuel 42595.02 gal
Fuel Economy 6.28 mpg
Avg Drive Load 47 %
Avg Vehicle Speed 52.5 mph

Trip Time 7939:58:47
Fuel Consumption 5.36 gal/h
Idle Time 2839:35:04
Idle Percent 35.76 %
Idle Fuel 1670.27 gal
Parked Regen Time 9:27:57


Incident Time: 05/21/14 11:07:50 (EST)

Incident Odometer: 346435.7 mi


Vehicle Speed (mph)




Engine RPM




Percent



Brake



Clutch



DDEC® Reports - Hard Brake

#1

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)

Vehicle ID: 1556

Driver ID:

Odometer: 346469.4 mi

Engine S/N: 472903S0045904

Trip Distance	267485.2 mi	Trip Time	7939:58:47
Trip Fuel	42595.02 gal	Fuel Consumption	5.36 gal/h
Fuel Economy	6.28 mpg	Idle Time	2839:35:04
Avg Drive Load	47 %	Idle Percent	35.76 %
Avg Vehicle Speed	52.5 mph	Idle Fuel	1670.27 gal
		Parked Regen Time	9:27:57

Incident Time: 5/16/2014 11:41:08 AM (EST) Incident Odometer: 346421.8 mi

Time	Vehicle Speed (mph)	Engine Speed (rpm)	Brake	Clutch	Engine Load (%)	Throttle (%)	Cruise	Diag. Code
-0:59	0.0	0	No	No	0.00	0.00	No	No
-0:58	0.0	0	No	No	0.00	0.00	No	No
-0:57	0.0	0	No	No	0.00	0.00	No	No
-0:56	0.0	0	No	No	0.00	0.00	No	No
-0:55	0.0	0	No	No	0.00	0.00	No	No
-0:54	0.0	0	No	No	0.00	0.00	No	No
-0:53	0.0	0	No	No	0.00	0.00	No	No
-0:52	0.0	0	No	No	0.00	0.00	No	No
-0:51	0.0	0	No	No	0.00	0.00	No	No
-0:50	0.0	0	No	No	0.00	0.00	No	No
-0:49	0.0	0	No	No	0.00	0.00	No	No
-0:48	0.0	0	No	No	0.00	0.00	No	No
-0:47	0.0	0	No	No	0.00	0.00	No	No
-0:46	0.0	0	No	No	0.00	0.00	No	No
-0:45	0.0	0	No	No	0.00	0.00	No	No
-0:44	0.0	0	No	No	0.00	0.00	No	No
-0:43	0.0	0	No	No	0.00	0.00	No	No
-0:42	0.0	0	No	No	0.00	0.00	No	No
-0:41	0.0	0	No	No	0.00	0.00	No	No
-0:40	0.0	0	No	No	0.00	0.00	No	No
-0:39	0.0	0	No	No	0.00	0.00	No	No
-0:38	0.0	0	No	No	0.00	0.00	No	No
-0:37	0.0	0	No	No	0.00	0.00	No	No
-0:36	0.0	0	No	No	0.00	0.00	No	No
-0:35	0.0	0	No	No	0.00	0.00	No	No
-0:34	0.0	0	No	No	0.00	0.00	No	No
-0:33	0.0	0	No	No	0.00	0.00	No	No
-0:32	0.0	0	No	No	0.00	0.00	No	No
-0:31	0.0	0	No	No	0.00	0.00	No	No
-0:30	0.0	0	No	No	0.00	0.00	No	No
-0:29	0.0	0	No	No	0.00	0.00	No	No
-0:28	0.0	0	No	No	0.00	0.00	No	No
-0:27	0.0	0	No	No	0.00	0.00	No	No
-0:26	0.0	0	No	No	0.00	0.00	No	No
-0:25	0.0	0	No	No	0.00	0.00	No	No
-0:24	0.0	0	No	No	0.00	0.00	No	No
-0:23	0.0	0	No	No	0.00	0.00	No	No
-0:22	0.0	0	No	No	0.00	0.00	No	No
-0:21	0.0	0	No	No	0.00	0.00	No	No
-0:20	0.0	0	No	No	0.00	0.00	No	No

DDEC® Reports - Hard Brake

#1

Print Date: 5/28/2014 11:49 AM

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)

Sole Reconstruction LLC

Vehicle ID:

1556

8706 S. 70th East Avenue

Driver ID:

Tulsa, OK 74133

Odometer:

346469.4 mi

918-639-9975

Engine S/N:

472903S0045904

Incident Time: 5/16/2014 11:41:08 AM (EST) Incident Odometer: 346421.8 mi

Time	Vehicle Speed (mph)	Engine Speed (rpm)	Brake	Clutch	Engine Load (%)	Throttle (%)	Cruise	Diag. Code
-0:19	0.0	0	No	No	0.00	0.00	No	No
-0:18	0.0	0	No	No	0.00	0.00	No	No
-0:17	0.0	0	No	No	0.00	0.00	No	No
-0:16	0.0	0	No	No	0.00	0.00	No	No
-0:15	0.0	0	No	No	0.00	0.00	No	No
-0:14	0.0	0	No	No	0.00	0.00	No	No
-0:13	0.0	0	No	No	0.00	0.00	No	No
-0:12	0.0	0	No	No	0.00	0.00	No	No
-0:11	0.0	0	No	No	0.00	0.00	No	No
-0:10	0.0	0	No	No	0.00	0.00	No	No
-0:09	0.0	0	No	Yes	0.00	0.00	No	No
-0:08	0.0	0	No	Yes	0.00	0.00	No	No
-0:07	0.0	0	No	Yes	0.00	0.00	No	No
-0:06	0.0	0	No	Yes	0.00	0.00	No	No
-0:05	13.0	0	No	Yes	0.00	0.00	No	No
-0:04	16.0	39	No	Yes	0.00	0.00	No	No
-0:03	16.0	82	No	Yes	0.00	0.00	No	No
-0:02	30.0	238	No	Yes	17.00	0.00	No	No
-0:01	38.0	609	No	Yes	16.00	0.00	No	No
0:00	10.5	601	No	Yes	16.50	0.00	No	No
+0:01	2.0	603	No	Yes	18.00	0.00	No	No
+0:02	0.5	598	No	Yes	19.00	0.00	No	No
+0:03	0.0	601	No	No	18.50	0.00	No	No
+0:04	0.0	597	No	No	19.50	0.00	No	No
+0:05	0.0	794	No	No	0.00	16.40	No	No
+0:06	0.0	769	No	No	7.00	9.60	No	No
+0:07	0.0	858	No	No	21.50	22.00	No	No
+0:08	0.0	866	No	No	20.50	22.00	No	No
+0:09	0.0	895	No	No	20.50	22.40	No	No
+0:10	0.0	621	No	No	16.00	2.00	No	No
+0:11	0.0	598	No	No	19.00	8.00	No	No
+0:12	0.0	605	No	No	43.50	37.20	No	No
+0:13	0.0	1118	No	No	21.00	29.60	No	No
+0:14	0.0	1122	No	No	17.50	26.80	No	No
+0:15	0.0	1126	No	No	17.50	26.80	No	No

DDEC® Reports - Hard Brake

#2

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)

Vehicle ID: 1556

Driver ID:

Odometer: 346469.4 mi

Engine S/N: 472903S0045904

Trip Distance	267485.2 mi	Trip Time	7939:58:47
Trip Fuel	42595.02 gal	Fuel Consumption	5.36 gal/h
Fuel Economy	6.28 mpg	Idle Time	2839:35:04
Avg Drive Load	47 %	Idle Percent	35.76 %
Avg Vehicle Speed	52.5 mph	Idle Fuel	1670.27 gal
		Parked Regen Time	9:27:57

Incident Time: 5/21/2014 11:07:50 AM (EST) Incident Odometer: 346435.7 mi

Time	Vehicle Speed (mph)	Engine Speed (rpm)	Brake	Clutch	Engine Load (%)	Throttle (%)	Cruise	Diag. Code
-0:59	0.0	0	No	No	0.00	0.00	No	No
-0:58	0.0	0	No	No	0.00	0.00	No	No
-0:57	0.0	0	No	No	0.00	0.00	No	No
-0:56	0.0	0	No	No	0.00	0.00	No	No
-0:55	0.0	0	No	No	0.00	0.00	No	No
-0:54	0.0	0	No	No	0.00	0.00	No	No
-0:53	0.0	0	No	No	0.00	0.00	No	No
-0:52	0.0	0	No	No	0.00	0.00	No	No
-0:51	0.0	0	No	No	0.00	0.00	No	No
-0:50	0.0	0	No	No	0.00	0.00	No	No
-0:49	0.0	0	No	No	0.00	0.00	No	No
-0:48	0.0	0	No	No	0.00	0.00	No	No
-0:47	0.0	0	No	No	0.00	0.00	No	No
-0:46	0.0	0	No	No	0.00	0.00	No	No
-0:45	0.0	0	No	No	0.00	0.00	No	No
-0:44	0.0	0	No	No	0.00	0.00	No	No
-0:43	0.0	0	No	No	0.00	0.00	No	No
-0:42	0.0	0	No	No	0.00	0.00	No	No
-0:41	0.0	0	No	No	0.00	0.00	No	No
-0:40	0.0	0	No	No	0.00	0.00	No	No
-0:39	0.0	0	No	No	0.00	0.00	No	No
-0:38	0.0	0	No	No	0.00	0.00	No	No
-0:37	0.0	0	No	No	0.00	0.00	No	No
-0:36	0.0	0	No	No	0.00	0.00	No	No
-0:35	0.0	0	No	No	0.00	0.00	No	No
-0:34	0.0	0	No	No	0.00	0.00	No	No
-0:33	0.0	0	No	No	0.00	0.00	No	No
-0:32	0.0	0	No	No	0.00	0.00	No	No
-0:31	0.0	0	No	No	0.00	0.00	No	No
-0:30	0.0	0	No	No	0.00	0.00	No	No
-0:29	0.0	0	No	No	0.00	0.00	No	No
-0:28	0.0	0	No	No	0.00	0.00	No	No
-0:27	0.0	0	No	No	0.00	0.00	No	No
-0:26	0.0	0	No	No	0.00	0.00	No	No
-0:25	0.0	0	No	No	0.00	0.00	No	No
-0:24	0.0	0	No	No	0.00	0.00	No	No
-0:23	0.0	0	No	No	0.00	0.00	No	No
-0:22	0.0	0	No	No	0.00	0.00	No	No
-0:21	0.0	0	No	No	0.00	0.00	No	No
-0:20	0.0	0	No	No	0.00	0.00	No	No

DDEC® Reports - Hard Brake

#2

Print Date: 5/28/2014 11:49 AM
Sole Reconstruction LLC
8706 S. 70th East Avenue
Tulsa, OK 74133
918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)
Vehicle ID: 1556
Driver ID:
Odometer: 346469.4 mi
Engine S/N: 472903S0045904

Incident Time: 5/21/2014 11:07:50 AM (EST) Incident Odometer: 346435.7 mi

Time	Vehicle Speed (mph)	Engine Speed (rpm)	Brake	Clutch	Engine Load (%)	Throttle (%)	Cruise	Diag. Code
-0:19	0.0	0	No	No	0.00	0.00	No	No
-0:18	0.0	0	No	No	0.00	0.00	No	No
-0:17	0.0	0	No	No	0.00	0.00	No	No
-0:16	0.0	0	No	No	0.00	0.00	No	No
-0:15	0.0	0	No	No	0.00	0.00	No	No
-0:14	0.0	0	No	No	0.00	0.00	No	No
-0:13	0.0	0	No	No	0.00	0.00	No	No
-0:12	0.0	0	No	No	0.00	0.00	No	No
-0:11	0.0	0	No	No	0.00	0.00	No	No
-0:10	0.0	0	No	No	0.00	0.00	No	No
-0:09	0.0	0	No	No	0.00	0.00	No	No
-0:08	0.0	0	No	No	0.00	0.00	No	No
-0:07	0.0	0	No	No	0.00	0.00	No	No
-0:06	0.0	0	No	No	0.00	0.00	No	No
-0:05	0.0	0	No	Yes	0.00	0.00	No	No
-0:04	0.0	0	No	Yes	0.00	0.00	No	No
-0:03	3.0	0	No	Yes	0.00	0.00	No	No
-0:02	3.5	79	No	Yes	14.00	0.00	No	No
-0:01	39.5	596	No	Yes	3.50	0.00	No	No
0:00	19.5	587	No	Yes	14.00	0.00	No	No
+0:01	4.0	594	No	Yes	15.00	0.00	No	No
+0:02	1.0	600	No	Yes	14.00	0.00	No	No
+0:03	0.0	598	No	Yes	15.50	0.00	No	No
+0:04	0.0	600	No	Yes	14.50	0.00	No	No
+0:05	0.0	599	No	Yes	15.00	0.00	No	No
+0:06	0.0	618	No	Yes	9.00	0.00	No	No
+0:07	0.0	589	No	Yes	17.50	0.00	No	No
+0:08	0.0	587	No	Yes	21.00	4.40	No	No
+0:09	0.0	574	No	Yes	36.50	8.00	No	No
+0:10	0.0	620	No	Yes	14.00	0.00	No	No
+0:11	0.0	629	No	Yes	10.50	0.00	No	No
+0:12	0.0	593	No	Yes	18.50	9.20	No	No
+0:13	0.5	569	No	Yes	44.00	13.20	No	No
+0:14	1.0	701	No	Yes	26.00	21.20	No	No
+0:15	1.5	848	No	Yes	27.50	26.80	No	No

DDEC® Reports - Last Stop Record

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)

Vehicle ID: 1556

Driver ID:

Odometer: 346469.4 mi

Engine S/N: 472903S0045904


Trip Distance 267485.2 mi
Trip Fuel 42595.02 gal
Fuel Economy 6.28 mpg
Avg Drive Load 47 %
Avg Vehicle Speed 52.5 mph

Trip Time 7939:58:47
Fuel Consumption 5.36 gal/h
Idle Time 2839:35:04
Idle Percent 35.76 %
Idle Fuel 1670.27 gal
Parked Regen Time 9:27:57


Last Stop Time: 05/28/14 10:48:21 (EST)

Last Stop Odometer: 346469.4 mi


Vehicle Speed (mph)




Engine RPM




Percent



Brake



Clutch



DDEC® Reports - Last Stop Record

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)

Vehicle ID: 1556

Driver ID:

Odometer: 346469.4 mi

Engine S/N: 472903S0045904

Trip Distance	267485.2 mi	Trip Time	7939:58:47
Trip Fuel	42595.02 gal	Fuel Consumption	5.36 gal/h
Fuel Economy	6.28 mpg	Idle Time	2839:35:04
Avg Drive Load	47 %	Idle Percent	35.76 %
Avg Vehicle Speed	52.5 mph	Idle Fuel	1670.27 gal
		Parked Regen Time	9:27:57

Last Stop Time: 5/28/2014 10:48:21 AM (EST) Last Stop Odometer: 346469.4 mi

Time	Vehicle Speed (mph)	Engine Speed (rpm)	Brake	Clutch	Engine Load (%)	Throttle (%)	Cruise	Diag. Code
-1:44	0.0	0	No	No	0.00	0.00	No	No
-1:43	0.0	0	No	No	0.00	0.00	No	No
-1:42	0.0	0	No	No	0.00	0.00	No	No
-1:41	0.0	0	No	No	0.00	0.00	No	No
-1:40	0.0	0	No	No	0.00	0.00	No	No
-1:39	0.0	0	No	No	0.00	0.00	No	No
-1:38	0.0	0	No	No	0.00	0.00	No	No
-1:37	0.0	0	No	No	0.00	0.00	No	No
-1:36	0.0	0	No	No	0.00	0.00	No	No
-1:35	0.0	0	No	No	0.00	0.00	No	No
-1:34	0.0	0	No	No	0.00	0.00	No	No
-1:33	0.0	0	No	No	0.00	0.00	No	No
-1:32	0.0	0	No	No	0.00	0.00	No	No
-1:31	0.0	0	No	No	0.00	0.00	No	No
-1:30	0.0	0	No	No	0.00	0.00	No	No
-1:29	0.0	0	No	No	0.00	0.00	No	No
-1:28	0.0	0	No	No	0.00	0.00	No	No
-1:27	0.0	0	No	No	0.00	0.00	No	No
-1:26	0.0	0	No	No	0.00	0.00	No	No
-1:25	0.0	0	No	No	0.00	0.00	No	No
-1:24	0.0	0	No	No	0.00	0.00	No	No
-1:23	0.0	0	No	No	0.00	0.00	No	No
-1:22	0.0	0	No	No	0.00	0.00	No	No
-1:21	0.0	0	No	No	0.00	0.00	No	No
-1:20	0.0	0	No	No	0.00	0.00	No	No
-1:19	0.0	0	No	No	0.00	0.00	No	No
-1:18	0.0	0	No	No	0.00	0.00	No	No
-1:17	0.0	0	No	No	0.00	0.00	No	No
-1:16	0.0	0	No	No	0.00	0.00	No	No
-1:15	0.0	0	No	No	0.00	0.00	No	No
-1:14	0.0	0	No	No	0.00	0.00	No	No
-1:13	0.0	0	No	No	0.00	0.00	No	No
-1:12	0.0	0	No	No	0.00	0.00	No	No
-1:11	0.0	0	No	No	0.00	0.00	No	No
-1:10	0.0	0	No	No	0.00	0.00	No	No
-1:09	0.0	0	No	No	0.00	0.00	No	No
-1:08	0.0	0	No	No	0.00	0.00	No	No
-1:07	0.0	0	No	No	0.00	0.00	No	No
-1:06	0.0	0	No	No	0.00	0.00	No	No
-1:05	0.0	0	No	No	0.00	0.00	No	No

DDEC® Reports - Last Stop Record

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)

Vehicle ID:

1556

Driver ID:

Odometer:

346469.4 mi

Engine S/N:

472903S0045904

Last Stop Time: 5/28/2014 10:48:21 AM (EST) Last Stop Odometer: 346469.4 mi

Time	Vehicle Speed (mph)	Engine Speed (rpm)	Brake	Clutch	Engine Load (%)	Throttle (%)	Cruise	Diag. Code
-1:04	0.0	0	No	No	0.00	0.00	No	No
-1:03	0.0	0	No	No	0.00	0.00	No	No
-1:02	0.0	0	No	No	0.00	0.00	No	No
-1:01	0.0	0	No	No	0.00	0.00	No	No
-1:00	0.0	0	No	No	0.00	0.00	No	No
-0:59	0.0	0	No	No	0.00	0.00	No	No
-0:58	0.0	0	No	No	0.00	0.00	No	No
-0:57	0.0	0	No	No	0.00	0.00	No	No
-0:56	0.0	0	No	No	0.00	0.00	No	No
-0:55	0.0	0	No	No	0.00	0.00	No	No
-0:54	0.0	0	No	No	0.00	0.00	No	No
-0:53	0.0	0	No	No	0.00	0.00	No	No
-0:52	0.0	0	No	No	0.00	0.00	No	No
-0:51	0.0	0	No	No	0.00	0.00	No	No
-0:50	0.0	0	No	No	0.00	0.00	No	No
-0:49	0.0	0	No	No	0.00	0.00	No	No
-0:48	0.0	0	No	No	0.00	0.00	No	No
-0:47	0.0	0	No	No	0.00	0.00	No	No
-0:46	0.0	0	No	No	0.00	0.00	No	No
-0:45	0.0	0	No	No	0.00	0.00	No	No
-0:44	0.0	0	No	No	0.00	0.00	No	No
-0:43	0.0	0	No	No	0.00	0.00	No	No
-0:42	0.0	0	No	No	0.00	0.00	No	No
-0:41	0.0	0	No	No	0.00	0.00	No	No
-0:40	0.0	0	No	No	0.00	0.00	No	No
-0:39	0.0	0	No	No	0.00	0.00	No	No
-0:38	0.0	0	No	No	0.00	0.00	No	No
-0:37	0.0	0	No	No	0.00	0.00	No	No
-0:36	0.0	0	No	No	0.00	0.00	No	No
-0:35	0.0	0	No	No	0.00	0.00	No	No
-0:34	0.0	0	No	No	0.00	0.00	No	No
-0:33	0.0	0	No	No	0.00	0.00	No	No
-0:32	0.0	0	No	No	0.00	0.00	No	No
-0:31	0.0	0	No	No	0.00	0.00	No	No
-0:30	0.0	0	No	No	0.00	0.00	No	No
-0:29	0.0	0	No	No	0.00	0.00	No	No
-0:28	0.0	0	No	No	0.00	0.00	No	No
-0:27	0.0	0	No	No	0.00	0.00	No	No
-0:26	0.0	0	No	No	0.00	0.00	No	No
-0:25	0.0	0	No	No	0.00	0.00	No	No

DDEC® Reports - Last Stop Record

Print Date: 5/28/2014 11:49 AM

Sole Reconstruction LLC

8706 S. 70th East Avenue

Tulsa, OK 74133

918-639-9975

Trip: 08/02/11 07:52:13 To 05/28/14 (EST)

Vehicle ID:

1556

Driver ID:

Odometer:

346469.4 mi

Engine S/N:

472903S0045904

Last Stop Time: 5/28/2014 10:48:21 AM (EST) Last Stop Odometer: 346469.4 mi

Time	Vehicle Speed (mph)	Engine Speed (rpm)	Brake	Clutch	Engine Load (%)	Throttle (%)	Cruise	Diag. Code
-0:24	0.0	0	No	No	0.00	0.00	No	No
-0:23	0.0	0	No	No	0.00	0.00	No	No
-0:22	0.0	0	No	No	0.00	0.00	No	No
-0:21	0.0	0	No	No	0.00	0.00	No	No
-0:20	0.0	0	No	No	0.00	0.00	No	No
-0:19	0.0	0	No	No	0.00	0.00	No	No
-0:18	0.0	0	No	No	0.00	0.00	No	No
-0:17	0.0	0	No	No	0.00	0.00	No	No
-0:16	0.0	0	No	No	0.00	0.00	No	No
-0:15	0.0	0	No	No	0.00	0.00	No	No
-0:14	0.0	0	No	No	0.00	0.00	No	No
-0:13	0.0	0	No	No	0.00	0.00	No	No
-0:12	0.0	0	No	No	0.00	0.00	No	No
-0:11	0.0	0	No	No	0.00	0.00	No	No
-0:10	0.0	0	No	No	0.00	0.00	No	No
-0:09	0.0	0	No	No	0.00	0.00	No	No
-0:08	0.0	0	No	No	0.00	0.00	No	No
-0:07	0.0	0	No	No	0.00	0.00	No	No
-0:06	0.0	0	No	No	0.00	0.00	No	No
-0:05	0.0	0	No	Yes	0.00	0.00	No	No
-0:04	0.5	0	No	Yes	0.00	0.00	No	No
-0:03	3.5	764	No	Yes	0.00	0.00	No	No
-0:02	3.5	592	No	Yes	6.00	0.00	No	No
-0:01	0.5	598	No	Yes	9.00	0.00	No	No
0:00	0.0	601	No	Yes	8.50	0.00	No	No
+0:01	0.0	596	No	No	10.50	0.00	No	No
+0:02	0.0	600	No	No	10.00	0.00	No	No
+0:03	0.0	600	No	No	10.00	0.00	No	No
+0:04	0.0	598	No	No	11.00	0.00	No	No
+0:05	0.0	602	No	No	9.50	0.00	No	No
+0:06	0.0	599	No	No	10.00	0.00	No	No
+0:07	0.0	603	No	No	9.00	0.00	No	No
+0:08	0.0	602	No	No	8.50	0.00	No	No
+0:09	0.0	600	No	No	9.50	0.00	No	No
+0:10	0.0	603	No	No	8.00	0.00	No	No
+0:11	0.0	598	No	No	10.00	0.00	No	No
+0:12	0.0	574	No	No	0.00	0.00	No	No
+0:13	0.0	280	No	No	0.00	0.00	No	No
+0:14	0.0	66	No	No	0.00	0.00	No	No
+0:15	0.0	0	No	No	0.00	0.00	No	No